

Rear trailing arm pick up points wallowed out

Posted by cbuzzetti - 03 May 2010 06:39

Hi Guys, I was taking apart my rear suspension today to check out bushings and mounting points.

During the process I saw that the mounting point for the rear trailing arm (alu) on the torsion tube is wallowed out.

Can this be repaired or do I have to change out complete torsion tube?

Can I use a heavy duty washer and weld it to the brackets provided it is in the correct spot?

I would prefer to do this since it is a pain to replace torsion tube and do complete alignment.

=====

Re:Rear trailing arm pick up points wallowed out

Posted by cbuzzetti - 07 May 2010 01:31

Local torsion tube located and will be installed but most likely not before next event. I will have the washers welded in place if I do not get T-tube installed.

I have no problem with anyone inspecting placement of washers or wanting to inspect any aspect of my car.

I am going through the rules line by line to make sure this car is legal.

That is how this all started. I was pulling the suspension for inspection and to report what bushings this car had.

=====